

## SIGHT UNIT SWALL ARMS TRILUX (SUSAT) (L12A1)





## Safety: The Trilux Source

The TRILUX lamp used in the SUSAT contains Tritium gas. In the event of breakage the following precautions are to be taken:

- 1. The escaping gas is not to be inhaled.
- 2. Cigarettes are to be extinguished immediately.
- 3. Broken parts are not to be handled with bare hands.
- 4. If a breakage occurs indoors, doors and windows are to be opened to allow the gas to clear, and any gas or flame heating system is to be turned off.
- 5. All breakages are to be reported to the Medical Officer and the unit armourer as soon as possible.